



<Ethernet line routing>
Do not position to other elements(R,L,C) to RJ-45 below
There should be no other signal under the differential signal.

WIZnet Co., Ltd.